

St. Joseph Apache Mission Restoration Project



Illustrated Progress Report for November 2010 through April 2011



Sam preparing a deep void for repointing.



One of the several deep voids.



Sam using his new skills scrapping back the top coat, making it smooth and uniform.



Josiah installing the new boiler unit.

Nikona repointing alcove arch.



Nikona's arch finished.



Kateri Circle and window donors, Andrew, Katherine, James and Lynda
(Photograph courtesy of David Tremblay)



Our Lady window installed.



Teresa working on the St. Thomas window.

Crew working away.

